


MORE PHOTOS OF FLOOD



Adjusted map of Tanjay with extent of flooded areas estimated. Red road is main highway route. Violet road is temporary detour.



Main bridge at height of flood. Note embankment



Later, water subsided but embankment eroded while steel beams and concrete pylons remain intact.



View from the eroded side of the bridge



Left, middle & right views of eroded side of bridge, Dec 19. Dept of Public Works personnel working to build back retaining wall and embankment.



Down stream view from New Tabuc bridge, height of flood



Same view after flood receded



Up stream view of damage, Tabuc side



Downed concrete fence, subdivision along Tabuc road



Downed portion of Serenity Cemetery side fence



View from Old Tabuc bridge

Below: Miscellaneous photos taken from Facebook posting of "Assenso Tanjay", probably different sources showing various scenes, described under each photo.



Matangad



Luca road



Ilaud



Untitled, but probably at Kasagingan



Banica river, Dumaguete



Dumaguete capitol
Danny Gil (ferngil@aol.com), 19 Dec 2011